

**SECRET**

OUT58789

S E C R E T 132335Z CITE [ ] 7455

1966 JUN 13 23 45Z 25X1  
25X1

1. CAMERA B-125 WAS USED IN MISSION 8100 FLOWN ON 11 JUNE 1966.  
PROCESSING WAS ACCOMPLISHED BY BARKSDALE.

## 2. ORIGINAL NEGATIVE:

14 JUN 1966

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: SLIGHT INBOARD AND OUTBOARD ROLLER CHATTER IS  
PRESENT INTERMITTENTLY THROUGHOUT THE MISSION. A MANUFACTURER'S  
SPlice IS LOCATED IN FRAME 0095.

C. 9L SIDE: A BAND OF FOG, PERPENDICULAR TO THE MAJOR AXIS,  
IS PRESENT ON FRAME 0000. THE MAJORITY OF THE POSITION INDICATOR  
LAMPS, NEAR THE DATA CHAMBER, ARE FAINT AND AT TIMES BARELY DETECT-  
ABLE. THE VERTICAL DOT POSITION INDICATOR LAMPS ARE BLOOMED.  
MINUTE HAIR LIKE OBSTRUCTIONS ARE INSIDE EACH FIDUCIAL. ULTRA-  
SONIC SPLICES WERE USED ON THE HEAD AND TAIL IDENTs AND ALSO BETWEEN  
FRAMES 1198/1199 AND 1508/1509. ASSOCIATED WITH THE SPLICES MADE  
ON FRAMES 299 AND 1509 ARE CREASES AND WRINKLES IN THE FILM, DUE  
TO MISALIGNMENT OF THE FILM DURING THE SPLICING PROCEDURE. STATIC  
TRACES OF FOG ARE PRESENT ON BOTH FILM EDGES THROUGHOUT THE MISSION.

D. BOTH SIDES: THE FRAMES ARE CONSECUTIVELY TITLED 0000  
THROUGH 1919.

E. THERE WERE NO MAJOR PROCESSING OR CAMERA MALFUNCTIONS.

## 3. POSITIVE:

DISTRIBUTION 2		
Cy No.	Office	Action
12	File	
	OS	
	ADMIN	
	SEC BR	
	P & DS	
	CSD	
	IPD	
	PD	
	PSD	
	PSD-ICB	
	TID	
	IAD	
	PAG	
	DIAXX-4	
	SPAD	
	NSA-LO	
	DIA-AP	

Advance copy  
Sanitized**SECRET**

-2-

- A. PI SUITABILITY IS GOOD.
- B. PRINTING AND PROCESSING WERE GOOD.
- C. CLOUDS AND HAZE DEGRADE APPROXIMATELY 40 PERCENT OF THE MISSION.

S E C R E T

--END OF MESSAGE--